




# Loading Paper in the Printer



## Quick Tip:

Fanning the paper will cause static electricity and the sheets to stick together.

**TIP:** When loading a ream of paper, simply “bend” the paper in different ways to minimize paper jams within the printer.