




# HP OfficeJet Enterprise Color MFP X585




## Clear jams in the left door

1. Open the left door.



2. Gently remove any visible paper from the rollers and delivery area.

**NOTE:** If the sheet tears, make sure that all fragments are removed before you resume printing. Do not use sharp objects to remove fragments.



3. Close the left door.

