



## HP Officejet Enterprise Color MFP X585 and HP Officejet Enterprise Color X555 - Replace the ink cartridges


### Replace the ink cartridges

The product uses four colors and has a different ink cartridge for each color: yellow (Y), cyan (C), magenta (M), and black (K).


1. Open the ink cartridge door.  
**1: Open the cartridge door**



2. Push the old ink cartridge inward to unlock it.  
**2: Release the ink cartridge**



3. Grasp the edge of the old ink cartridge and then pull the cartridge straight out to remove it.  
**3: Remove the ink cartridge**




4. Remove the new ink cartridge from the packaging.  
**4: Unpack the ink cartridge**



5. Do not touch the gold-colored metal contacts of the ink cartridge. Fingerprints on the contacts can cause print-quality problems.  
**5: Do not touch the contact**



6. Insert the new ink cartridge into the product. Push the cartridge until it “clicks” into place.  
**6: Insert the ink cartridge**



7. Close the ink cartridge door.  
**7: Close the cartridge door**



8. Place the old cartridge in the box and refer to information about recycling used ink cartridges on the ink cartridge box.