



# HP OfficeJet Enterprise Color MFP X585



## Clear jams in the output bin

1. Look for jammed paper in the output bin area.



2. Remove any visible media.

**NOTE:** If the sheet tears, make sure that all fragments are removed before resuming printing.



3. Open and then close the left door to clear the message.

