

HP LaserJet P4010 and P4510 Series Printers



Load Trays
装入紙盘
Tálcák betöltése
Зарузка лотков


Charger les bacs
Plnění zásobníků
용지함 넣기
Fylla på fack

Fächer laden
Fyld bakker
Legge i skuffer
装入紙匣


Caricamento dei vassoi
Laden vullen
Ładowanie podajników
Tepsilere Ortam Yerleřtirme

Carga de bandejas
Lokeroiden asettaminen
Carregar bandejas
Càrrega de safates


トレイのセット




1




2





3




4




5




1





2




3




4




1



2



3



4

